

Councillor Briefing Notes Meeting 26th April 2022 – Appendix 2

Play Park Inspection Report 2022 – Remedial Actions Identified.

Page	Ancillary Items	Concern	Risk	Tasks / Action required	Decision / Completed
A4	General Surface	Mole Hills present	Low		
A7	Seating Bench	Slats exceed 30mm	V low	No reasonably practical action is identified	
A8	Signage	No dogs and ownership signage required	Low	Order and fit signs	Signs ordered – to be fitted
	Primary Items				
P2	Rope Bridge	Timber Decay throughout	Medium	Replace decayed components where possible and plan replacement item	
	Wooden posts	Strimmer damage – likely to accelerate timber rot	Low	Prevent further damage	
P3	Chain Cover seat Zip Wire	Chain cover prevented inspection of chain links	Medium	Chain was replaced/new March 2022	
P4	Surface – grass matting is parting	Grass matting is parting	Medium	Make level	
P5	Climber A frame	Surfacing below not compliant	Medium	Install appropriate surface	
P6	Cycle course - Arches	Loose in ground	Low	Reset	
P7	Cycle Course - Surface	Has holes in it	Medium	Repair surface	
	Cycle Course - Ramps	Surface is uneven	Low	Make good	
P8	Multiplay	Equipment is dirty/algae covered	Low	Clean	
P10`	Rocker – Rocking Horse	Gaps between tiles	Medium	Eliminate gaps	
P11	Rocker – Seesaw	Bearings are worn Centre axis showing signs of wear	Medium	Replace worn bearings	

P13	Rotator – Stand on	Significant corrosion	Medium	De-scale back to good metal and coat with lead free paint. Repair as necessary when corrosion is removed.	
P14	Swing – mixed	Shrinkage and separation of surface – trip hazard	Medium	Re-glue and fill gaps and joints	
P15	Swing seat – single point	Associated with injury due to high spin speeds when chains twisted v tightly	Medium	Check regularly for ensure no unauthorised additions and that bearing rotates freely	
		Bearings are noisy	Medium	Dismantle and inspect according to manufacturers instructions	
		Surface needs repair	Medium	Matting needs repairing	
P19	MUGA – single end	Surface is wearing	Low	Repair	